SRB CRITICAL ITEMS LIST

SUBSYSTEM: ELECTRICAL AND INSTRUMENTATION

ITEM NAME: SRB OF Nonwatertight Reusable Cables 131W102R P4 (231W102R P4) and 131W105R P3

(231W105R P3) (Rate Gyro 1(LSRB), 2(RSRB), 3(LSRB) and 4(RSRB) Pitch/Yaw Rate Outputs)

PART NO.: 10400-0106 (10400-0117) FM CODE: A13

10400-0107 (10400-0118)

ITEM CODE: 50-04-X31 REVISION: Basic

CRITICALITY CATEGORY: 1R REACTION TIME: Seconds

NO. REQUIRED: 1 each DATE: March 1, 1995

CRITICAL PHASES: Boost SUPERCEDES: March 1, 1994

FMEA PAGE NO.: D-733 ANALYST: R. Smith/A. Craft

SHEET 1 OF 2 APPROVED: P. Kalia

FAILURE MODE AND CAUSES: Loss of three of four Rate Gyro Pitch and Yaw rate outputs in three out of four cables due to:

 One pin or wire open caused by: open crimp, open wire, broken/bent pin, unseased pin, broken pin locking mechanism, corroded pin.

- One pin or wire short to ground caused by: bent pin, contamination in connector, insulation breakdown, frayed shielding, abraded or cut insulation.
- 6 Loss of connector caused by: connector not fully mated, mechanical overstress, failure of locking mechanism.

FAILURE EFFECT SUMMARY: Loss of three of four Rate Gyros rate detection results in flight instability leading to loss of mission, vehicle and crew.

REDUNDANCY SCREENS AND MEASUREMENTS:

- Pass All cables are system tested during ground turnsround sequence.
- Pass Rate Gyto 1(LSRB), 2(RSRB), 3(LSRB) and 4(RSRB) Pitch and Yaw rate measurements E79R1(2)410C, B79R1(2)412C, B79R1(2)411C and B79R1(2)413C.
- 3) Pass No credible causes.

FM Code: 50-04-X31-A13 Date: March 1, 1995

RATIONALE FOR RETENTION:

- A. DESIGN Per Appendix A Section # Y
- B. TESTING
- VENDOR RELATED Per Appendix B Section # 1A.
- 2) KSC RELATED Per Appendix B Section # IIA
- 3) SYSTEM/ UNIQUE FUNCTIONAL

Cables are tested during ACO per 10REQ-0021, para. 1.2.2.19.1 (Rate Gyro Assembly power on and SMRD Test) (open, short or loss of connector)

Cables are tested per OMRSD File II, Vol. 1, requirement number \$00000.643 (RGA Torque Test).

The last time cables are tested is during final countdown per OMRSD File II, Vol. 1, requirement number S00FF0.230. (RGA Torque Test)

- C. INSPECTION
- VENDOR RELATED For Appendix C Section # 1 (Crimped Connector)
- 2) KSC RELATED Per Appendix C Section # IIA 1.2.3.4, and 2
- D. FAILURE HISTORY

Failure Histories may be obtained from the PRACA database.

E. OPERATIONAL USE

Not applicable to this failure mode.

Supercedes: March 1, 1994 DR Document, RA-21